
NAVAL AIR DEVELOPMENT CENTER WARMINSTER PA AIRCRAFT -- ETC F/6 11/6
THE DEVELOPMENT OF AMLGUARD, A CLEAR, WATER DISPLACING, CORROSI-- ETC(U)
MAY 79 6 J PILIA
NADC-78220-60
NL UNCLASSIFIED NL 1 OF | AD A071617 END DATE FILMED 8 - 79

AD-A071 617



REPORT NO. NADC-78220-60



ADA 071617

THE DEVELOPMENT OF AMLGUARD, A CLEAR, WATER DISPLACING, CORROSION PREVENTIVE COMPOUND


Gabriel J. Pilla
Aircraft and Crew Systems Technology Directorate
NAVAL AIR DEVELOPMENT CENTER
Warminster, Pennsylvania 18974

11 May 1979

Final AIRTASK NO. WF54-593-201 Work Unit No. ZM301

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED

Prepared for NAVAL AIR SYSTEMS COMMAND Department of the Navy Washington, D. C. 20361



79 07 23 136

DUC FILE COPY

# NOTICES

REPORT NUMBERING SYSTEM - The numbering of technical project reports issued by the Naval Air Development Center is arranged for specific identification purposes. Each number consists of the Center acronym, the calendar year in which the number was assigned, the sequence number of the report within the specific calendar year, and the official 2-digit correspondence code of the Command Office or the Functional Directorate responsible for the report. For example: Report No. NADC-78015-20 indicates the fifteeth Center report for the year 1978, and prepared by the Systems Directorate. The numerical codes are as follows:

CODE	OFFICE OR DIRECTORATE
00	Commander, Naval Air Development Center
01	Technical Director, Naval Air Development Center
02	Comptroller
10	Directorate Command Projects
20	Systems Directorate
30	Sensors & Avionics Technology Directorate
40	Communication & Navigation Technology Directorate
50	Software Computer Directorate
60	Aircraft & Crew Systems Technology Directorate
70	Planning Assessment Resources
80	Engineering Support Group

PRODUCT ENDORSEMENT - The discussion or instructions concerning commercial products herein do not constitute an endorsement by the Government nor do they convey or imply the license or right to use such products.

APPROVED BY:

STURM

DATE: 5/11/79

# UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)


REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER 2. GOVT ACCESSION NO	3. RECIPIENT'S CATALOG NUMBER
NADC-78220-60	
4. TITLE (and Subtitle)	5. TYPE OF REPORT & PERIOD COVE
THE DEVELOPMENT OF AMLGUARD, A CLEAR, WATER	9
DISPLACING, CORROSION PREVENTIVE COMPOUND	FINAL rent
2 2 2 4 1	6. PERFORMING ORG. REPORT NUMBE
	1
7. AUTHOR(e)	8. CONTRACT OR GRANT NUMBER(*)
CARRIET T DITTA	
GABRIEL J. PILIA (16) F54592	
9. PERFORMING ORGANIZATION NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, TA
Naval Air Development Center	1
Aircraft and Crew Systems Technology Directorat	AIRTASK NO. WF54~593-201
Warminster, Pennsylvania 18974	Work Unit No. ZM301
11. CONTROLLING OFFICE NAME AND ADDRESS	12. REPORT DATE
Naval Air Systems Command	11 May 1979
Department of the Navy	19. NUMBER OF PAGES
Washington, D. C. 20361	66
14. MONITORING AGENCY NAME & ADDRESS(II different from Controlling Office)	15. SECURITY CLASS. (of this report)
15	
(12)6/m	UNCLASSIFIED
Control of the	15a. DECLASSIFICATION/DOWNGRADIN
homeomorphism (	SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  Approved for Public Release; Distribution Unlim	nited.
	F54592
Approved for Public Release; Distribution Unlim  17. DISTRIBUTION STATEMENT (of the ebetract entered in Block 20, if different fr  18. SUPPLEMENTARY NOTES  19. KEY WORDS (Continue on reverse side if necessary and identify by block number Water Displacing	F54592
Approved for Public Release; Distribution Unlim  17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, If different for  18. SUPPLEMENTARY NOTES  19. KEY WORDS (Continue on reverse side II necessary and identify by block number Water Displacing Corrosion Protection	F54592
Approved for Public Release; Distribution Unlim  17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, If different for  18. SUPPLEMENTARY NOTES  19. KEY WORDS (Continue on reverse side II necessary and identify by block number Water Displacing Corrosion Protection Clear	F54592
Approved for Public Release; Distribution Unlim  17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, If different for  18. SUPPLEMENTARY NOTES  19. KEY WORDS (Continue on reverse side II necessary and identify by block number Water Displacing Corrosion Protection	F54592
Approved for Public Release; Distribution Unlim  17. DISTRIBUTION STATEMENT (of the obstract entered in Block 20, if different for  18. SUPPLEMENTARY NOTES  19. KEY WORDS (Continue on reverse side if necessary and identify by block number Water Displacing Corrosion Protection Clear Dry Film  20. APSTRACT (Continue on reverse side if necessary and identify by block number, Previous corrosion control treatment used on ex of naval aircraft required the application of t displacing, corrosion preventive compound, MIL- film material), followed by the application of compound MIL-C-16173, Grade 4 (a brown, tacky m	posed corrodible surfaces wo materials a water C-81309 (a brown, thin corrosion preventive aterial). This combinatio
Approved for Public Release; Distribution Unlim  17. DISTRIBUTION STATEMENT (of the obstract entered in Block 20, 11 different for  18. SUPPLEMENTARY NOTES  19. KEY WORDS (Continue on reverse side if necessary and identify by block number Water Displacing Corrosion Protection Clear Dry Film  10. APSTRACT (Continue on reverse side if necessary and identify by block number, Previous corrosion control treatment used on ex of naval aircraft required the application of t displacing, corrosion preventive compound, MILfilm material), followed by the application of	posed corrodible surfaces wo materials a water C-81309 (a brown, thin corrosion preventive aterial). This combination osited a rather unsightly


S/N 0102- LF- 014- 6601

UNCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

## 20 ABSTRACT (cont'd)

displacing, corrosion preventive properties resulting in the deposit of a clear, dry, flexible film was essential. The recently developed compound AMLGUARD, designed with the above characteristics, fulfilled these objectives and performed successfully during laboratory tests and fleet evaluations. Military Specification MIL-C-85054(AS) titled, Corrosion Preventive Compound, Water Displacing, Clear (AMLGUARD) was issued 23 March 1977. National stock numbers, 8030-01-041-1596 and 8030-01-045-4780 have been issued for the 16 ounce aerosol containers and the one quart bulk containers, respectively.





#### SUMMARY

#### INTRODUCTION

Exterior surfaces of naval aircraft require constant maintenance to minimize corrosion. MIL-C-81309, water displacing corrosion preventive compound and MIL-C-16173, Grade 4 were extensively used by organizational and intermediate levels of maintenance to protect damaged areas of painted surfaces, but were unsatisfactory for several reasons. Both compounds being soft, pick up corrosive salt particles, dirt, and are unsightly in appearance. There was obviously a need for a compound that would produce a clear, dry, flexible film with water displacing, corrosion preventive properties. The Naval Air Development Center was tasked under AIRTASK WF 54-593-201, Work Unit No. ZM301 to develop such a material. The compound developed which fulfills this need has been designated AMLGUARD.

This report provides a detailed history of AMLGUARD, its formulation, the extensive laboratory testing program undertaken to evaluate the performance and chemical characteristics of the compound and the results of field tests conducted by the fleet.

#### RESULTS

A compound, AMLGUARD, has been developed which provides the three required performance characteristics; (1) ability to displace water, (2) protect against corrosion, and (3) dry to a clear, hard film.

The compound's water-displacing property depended primarily on the type solvent used in the formulation and its compatibility with other constituents without interfering with corrosion protection and film properties. The displacement or removal of water including salt water from a metallic surface was achieved by using a petroleum base solvent in the formulation. The drying time was controlled to allow water displacement to occur before a film could form over water droplets and entrap them. The compound's drying time was controlled by the selection of solvents used in the formulation based on their evaporation rate.

The use of silicone alkyd resin and silicone resin blended with small percentages of petroleum sulfonate and organic phosphate offer suitable corrosion protection without adversely affecting the required film properties of the newly developed compound, "AMLGUARD." (See Figure 1.)

AMLGUARD combines the properties of both specification compounds MIL-C-81309 and MIL-C-16173, Grade 4 in addition to being clear and dry without cosmetically affecting the appearance of the aircraft as shown in Figure 2.

The removal of AMLGUARD is achieved by wiping the surface with a solvent dampened cloth. Some solvents listed in Technical Manual, NAVAIR 01-1A-509,

Aircraft Weapons Systems Cleaning and Corrosion Control, are suitable for removing the compound. Advance surface analytical techniques conducted at Lehigh University confirm that, AMLGUARD can be totally removed from aluminum surfaces. This is particularly noteworthy since the compound contains silicone resins which are believed to be persistent and to affect subsequent paint adhesion. During the removal evaluation it was noted that MIL-C-43616 specification cleaners removed most of the AMLGUARD from aluminum test specimens. Consequently, where MIL-C-43616 specification cleaners are used during aircraft washing operations, the protective coating of AMLGUARD may be removed after a number of washings.

The evaluation of AMLGUARD conducted by fleet personnel supports results obtained during laboratory testing. Field reports indicate some additional uses of AMLGUARD; e.g., (1) on leading edges of aircraft wings and helicopter blades where the compound provides some erosion resistance for the underlying paint system; (2) on exhaust and gun blast areas where it facilitates the subsequent cleaning of those areas. AMLGUARD coated surfaces release dirt more easily as stated in Appendix A. Fleet endorsement of the compound will be found in Appendices A through F.

The new material, Corrosion Preventive Compound, Water Displacing, Clear (AMLGUARD) under Military Specification MIL-C-85054(AS), is available through the Federal Supply System. The compound packaged in both 16-ounce aerosol containers and one-quart bulk containers can be obtained using the national stock numbers 8030-01-041-1596 and 8030-01-045-4780 respectively.

The procedures for use of MIL-C-85054(AS) (AMLGUARD) for Aircraft Corrosion Prevention/Control can be found in Appendix K.

#### CONCLUSIONS

- 1. The water displacing, corrosion preventive compound, AMLGUARD (MIL-C-85054), provides a degree of corrosion protection to exterior aircraft surfaces that is superior to other in-service treatment materials currently available. It combines the properties of MIL-C-81309 and MIL-C-16173, Grade 4 and in addition, is dry, clear, and without effect on the cosmetic appearance of the aircraft.
- 2. Materials conforming to MIL-C-85054 can be substituted for MIL-C-81309 or MIL-C-16173 Grade 4 except on parts which require a lubricated surface, electrical contact areas, form-in-place gaskets, and removable fasteners.
- 3. AMLGUARD could be used as a replacement for touch-up paint for aircraft on board ships. AMLGUARD has salt-water displacing properties which MIL-P-23377 and MIL-C-81773 do not. AMLGUARD does not require as elaborate surface preparation. Its use would also permit reduction of inventory of various paint systems and colors during aircraft deployment and eliminate worry about isocyanate toxicity.

#### RECOMMENDATIONS

- 1. It is recommended that MIL-C-85054(AS), Corrosion Preventive Compound, Water Displacing, Clear (AMLGUARD), be used on corroded or corrosion prone areas of naval aircraft provided there are no closely fitted moving or sliding parts involved. The characteristic of AMLGUARD to produce a dry film when applied can impede the operation of these type parts.
- 2. Although the use of AMLGUARD on exterior of electrical connectors is acceptable, its use should be avoided on electrical contacts and connectors where metal to metal continuity and circuit integrity is necessary, due to its good insulating properties.
- 3. It is recommended that AMLGUARD be used in place of touch-up paint for corrodible surfaces on fleet deployed aircraft.

#### FUTURE WORK

Consideration should be given to continuing work on AMLGUARD in the following areas:

- l. A pigmented compound with equivalent properties to AMLGUARD be developed to enhance its use as a replacement for touch-up paint for ship-board operations.
- 2. Modifications to AMLGUARD be formulated for use on aircraft with countermeasure coatings.
- Update the present solvent system used in the AMLGUARD formulation, so as to comply with local air quality requirements.

THIS PAGE INTENTIONALLY LEFT BLANK

# TABLE OF CONTENTS

				Page No.
SUMMARY				i
Introduction				i
Results				i
Conclusions				ii
Recommendations				iii
Future Work				iii
INVESTIGATIVE PROCEDURE				1
Selection of Materials				1
FORMULATION MIXING PROCEDURE				1
LABORATORY TESTS AND RESULTS				2
Protection Properties				2
1. Test Specimens				2
2. Humidity Test	• • • •			2
3. Sulfurous Acid/Synthetic				2
4. Five Percent Salt Spray				3
<ol><li>Synthetic Sea Water Disp</li></ol>	placement	Test		4
FILM PROPERTIES				5
Clarity				- 5
Removability				5
PHYSICAL TESTS			10.00	7
Flexibility				7
Oil Resistance Test				7
Effects on Painted Surfaces				8
Flash and Fire Properties				8
Effects on Acrylic Plastic				
Storage Stability and Shelf Life				9

# TABLE OF CONTENTS (CONT'D)

	Page No.	2.
FLEET EVAI	LUATION	
APPENDIX A	A A-1	
APPENDIX I	в	
APPENDIX (	C-1	
APPENDIX I	D-1	
APPENDIX I	E-1	
APPENDIX I	F	
APPENDIX (	G	
APPENDIX I	н	
APPENDIX	I	
APPENDIX .	J	
APPENDIX	К	
	LIST OF TABLES	
Table No.	Page N	_
I	Results of Auger Electron Spectroscopy Analysis 10	
II	AMLGUARD Flexibility Test	
III	AMLGUARD Oil Resistance Test	
IV	AMLGUARD Field Evaluation Data Evaluation Criteria 13	
	LIST OF FIGURES	
Figure No	Page No.	<u>o</u> .
1	5% Salt Spray Exposure	
2	Aircraft Corrosion Preventive Visual Comparison 17	
3	AMLGUARD Tinted Blue for Discernibility on Aircraft Surfaces	

# LIST OF FIGURES (CONT'D)

Figure No	•	Page No.
4	Humidity Cabinet 100% Relative Humidity @ $120^{\circ}$ F	19
5	Humidity Exposure Test	20
6	Sulfurous Acid/Synthetic Sea Water Spray Test	21
7	Sulfurous Acid/Synthetic Sea Water Spray Test in Progress	22
8	Simulated Carrier Deck Environment H <sub>2</sub> SO <sub>3</sub> /Sea Spray Test	23
9	Sulfurous Acid Synthetic Sea Water Spray Test Specimen	24
10	Accelerated Laboratory Test Simulated Carrier Deck Environment	25
11	5% Salt Spray $\mathrm{SO}_2$ 90 Day Exposure Test Specimens	26
12	5% Salt Spray SO <sub>2</sub> 90 Day Exposure Test Specimens (Solvent Wiped)	27
13	Synthetic Sea Water Displacement Test	28
14	Synthetic Sea Water Displacement Test	29
15	Synthetic Sea Water Displacement Panels after Exposure to 100% Humidity	30
16	Wet Tape Test	31

THIS PAGE INTENTIONALLY LEFT BLANK

#### INVESTIGATIVE PROCEDURE

# Selection of Materials

The composition of AMLGUARD consists of a combination of resins, solvents, a thickening agent, a coupling agent and corrosion inhibitors. The major constituents in the formulation are the silicone alkyd resin and the silicone resins which were selected for their resistance to weathering, corrosion protection and heat stability, those service and performance conditions common to naval aircraft. Basically, the combined resins in the formulation provide a physical barrier from corrosive shipboard stack gases and sea spray. The solvents present in the compound have several functions, they promote water displacement, assist leveling of the compound, aid drying time, solubilize the thickening agent and facilitate compatibility between constituents. The inhibitors provide corrosion protection for the metal substrate. The thickening agent is added to give body to the compound to prevent run off and to achieve a one mil (0.001 in.) (0.025 MM) film thickness with two spray applications. The compound's drying time was controlled by selection of solvents based on their evaporation rate without destroying the water displacement properties and compatibility with formulation constituents. The drying time was controlled to accomplish water displacement before a film could form over water droplets. The early version of the compound being virtually colorless by design made it almost impossible to differentiate where it had been applied on the aircraft surface without close observation. The fleet personnel evaluating the new compound indicated that some coloration would be desirable to distinguish where the AMLGUARD was applied and in what quantity. A blue dye was added to the compound for discernibility (Figure 3) on aircraft surfaces.

The following formulation of the Clear, Water Displacing, Corrosion Preventive Compound was developed with characteristics stated herein to comply with naval aircraft performance and withstand environmental conditions.

	Parts by Weight (Grams)
1. Isopropanol (Navy Stock)	46.0
2. Aromatic Hydrocarbon, Amsco Solvent "G" (American Mineral	
Spirits Company)	212.0
3. Trichlorotrifluoroethane, Freon TF (E. I. Du Pont)	286.0
4. Ethyl Cellulose T-200 (Hercules Powder)	4.0
5. Barium Sulfonate, NaSul BSN (R. T. Vanderbilt Co.)	40.0
6. Alkyl Ammonium Organic Phosphate, Rust Preventive R.P. No. 2	
(E. I. Du Pont)	10.0
7. Silicone Varnish DF-88 (General Electric)	51.0
8. Silicone Resin SR-82 (General Electric)	51.0
9. Silicone Alkyd Resin, Varkyd 385-50E (McCloskey Varnish Co.)	300.0
	1000.0

#### FORMULATION MIXING PROCEDURE

The first three ingredients, the solvent portion, are added singly in the order stated above while stirring. An Oil Blue A dye is added (2.0 milligrams/100 c.c.) to the blended solvent mixture while stirring, allowing five minutes mixing time to dissolve the dye. Ethyl/Cellulose T-200 is then added to the solvent mixture by slowly sifting the powder into the mix while stirring, if no lumps are evident, approximately 15-20 minutes mixing time is necessary to dissolve the ethyl cellulose powder. Once the ethyl cellulose is dissolved

ingredients are added in the sequence listed above while the mixture is continuously stirred. Allow five minutes mixing time after adding each ingredient. After the five minute mixing time of each ingredient, the batch shall be checked for weight loss due to solvent evaporation. Add trichloro-trifluoroethane (Freon TF) as required to make up the difference in weight.

LABORATORY TESTS AND RESULTS

## Protection Properties

## 1. Test Specimens

AISI 1010 steel was used for most of the test work due to its rapid corrosion rate which enables a quick determination of the corrosion protection of each experimental formula. The 1010 steel is aircraft quality grade conforming to specification MIL-S-7952.

## 2. Humidity Test

ASTM D1748-70 \* was used to determine the experimental compound's ability to protect 1010 steel when exposed to a sustained 100% humidity environment for prolonged periods. This simulates a climatic condition that some naval aircraft will experience during a deployment. The test utilizes a humidity chamber where a condensing condition at  $+120^{\circ}$ F (49°C) is produced by air bubbling through diffuser stones which are submerged in water heated to  $+140^{\circ}$ F (60°C) (Figure 4). A constant rotating specimen holder is used to suspend the test specimens in the humidity chamber to assure uniform moisture deposit on each test specimen.

The compound under test was applied to a 1010 steel specimen (2"x4"x1/8" thick) (50mm x 101mm x 3mm) using one of two application methods. The first method employs a Fisher-Paye Dip Coater, whereby, the test specimen is dipped in the test compound and is withdrawn at a slow uniform rate of 4"/minute (101mm/minute). This method deposits a thin uniform film on the test specimen approximately one tenth mil (0.0001 in.) (0.0025 mm) thick when dry using this type compound. The alternate method of application consisted of spraying a 1010 steel test specimen with the test compound from either an aerosol can or a MIL-S-22805 aerosol spray kit. This method deposited a heavier less uniform film on the test specimen, approximately five tenth's of a mil (0.0005 in.) (0.0125 mm) thick when dry, with a one-coat application. After the compound air dried overnight the test specimen was subjected to the humidity chamber with the polished side of each specimen facing the rotational direction of the specimen holder. The specimens were observed daily for corrosion. After 65 days of exposure to the humidity environment, the test specimens were removed from the chamber. To indicate the compound's protective ability, the AMLGUARD film was removed. When compared to a blank 1010 steel test specimen with no protection and exposed for 24 hours in the same environment there was significant difference as can be noted in Figure 5.

## 3. Sulfurous Acid/Synthetic Sea Water Test

The Sulfurous Acid/Synthetic Sea Water Spray Test is depicted in Figure 6.

\* Standard Test Method for Rust Protection by Metal Preservatives in the Humidity Cabinet

The significance of this test was to determine the corrosion protection capability of the experimental compound under a simulated aircraft carrier deck environment. This test was used for the development of the forerunner Corrosion Preventive Compound MIL-C-81309. Basically, the test is a cycling of sulfurous acid/synthetic sea water solution atomized for one hour by air pressure to produce a fog or mist (Figure 7) and air dried for three hours. Sulfurous acid is the acid produced when carrier stack gases containing sulfur dioxide (combustion products of bunker C fuel) combine with water vapor from the sea spray. Reagent grade sulfurous acid was added to the synthetic sea water in the percentage necessary to achieve corrosion equivalent to that obtained with the combustion products of bunker C fuel. Synthetic sea water used in the test simulates natural sea water. The synthetic sea water consists of chemical salts and their percentages approximating those existing in a composite of natural sea water. Details concerning the test procedure are explained in Naval Air Development Center report No. AML 2436 titled, "Development of Environment Wet Test Chamber for Simulating Carrier Deck and Other Corrosive Environment", dated 11 May 1966. Test specimens consisting of 1010 steel measuring 2-1/8 inches (54 mm) in diameter by 1/16 of an inch (1.5 mm) thick were used for this test. The test specimens were coated in the same manner used to prepare the humidity chamber test specimens, by either the Fisher Payne Dip Coater method and/or the spraying method, from either the aerosol package or the MIL-S-22805 aerosol spray kit. The test specimens, spray coated and air dried overnight, were subjected to the simulated carrier deck environment (H2SO3/Sea Spray Test). Comparatively, Figure 8 shows the specimens treated with AMLGUARD and exposed for 10 cycles were adequately protected from the corrosive environment, whereas, the untreated specimen when exposed for one cycle, severely corroded. Figure 9 depicts a typical salt deposit after five cycles.

A dissimilar metal corrosion test was conducted to demonstrate the effectiveness of AMLGUARD on a magnesium-cadmium plated steel coupling on both painted and unpainted specimens. The test consisted of a specification QQ-M-44 magnesium disc two inches (51 mm) in diameter by 1/4" inch (6.3 mm) thick, with a countersunk hole in the center to accommodate a cadmium-plated steel aircraft fastener. A pair of disc assemblies were painted and another pair were left bare. A painted disc assembly and a bare disc assembly were treated with AMLGUARD and air dried overnight. The four discs were subjected to the SO2/salt spray test mentioned above. The untreated specimens both painted and unpainted were exposed for one hour to the corrosive environment and showed severe corrosion or attack. The AMLGUARD treated specimens both painted and unpainted were exposed for four hours to the same environment and displayed no evidence of attack, see Figure 10.

#### 4. Five Percent Salt Spray Test

Salt spray tests were also used to evaluate the corrosion protection ability of the experimental formulations. One test was conducted in a salt fog cabinet meeting the requirements of ASTM Bll7-73 Appendix I. five percent salt fog was constantly discharged, seven days a week. Ideally, many test panels can be exposed at one time to obtain quick comparative results.

1010 steel panels measuring 3" x 6" (76 mm x 152 mm) were painted and air dried for seven days. The panels were scribed with an X on their long axis down to the substrate metal. One half of the panel was treated with the corrosion preventive compound and air dried overnight before being exposed in the five percent salt cabinet. To illustrate the effectiveness of the test and the protection of the AMLGUARD see Figure 1.

Early experimental formulation testing was conducted on 3" x 6" (76 mm x 152 mm) 7075 alclad aluminum panels coated with Specification MIL-P-23377, Primer Coating, Epoxy Polyamide, Chemical and Solvent Resistant and topcoated with Specification MIL-C-81773, Coating, Polyurethane, Aliphatic, Weather Resistant. Two panels were used per test, both were scribed with an X through the paint system down to the aluminum substrate. One panel was treated with the experimental preservative, the other left untreated. Both were subject to five percent salt/SO2 spray, in a cabinet meeting the requirements of ASTM B117-73 Appendix I. The environment in the cabinet is a continuous five percent salt spray fog where sulfur dioxide gas is injected at a flow rate of 1 c.c./min./cu.ft.(1 cc/min./0.03 m) of cabinet, for 1 hr/ 6 hr cycle (four times daily). This again simulates the environment of an aircraft carrier with stack gases and sea spray. Details of the test procedure is presented in Naval Air Development Center report No. NADC-77252-30 titled, Accelerated Laboratory Corrosion Test for Materials and Finishes used in Naval Aircraft. A 90 day exposure to that environment produced results which clearly demonstrated the protective quality of the preservative. Results are displayed in Figures 11 and 12. The painted aluminum test specimens were not further used due to the length of time required to obtain significant results. Subsequent testing was conducted primarily on 1010 steel which produced faster results.

# 5. Synthetic Sea Water Displacement Test

The following test was conducted simulating a corrodible aircraft surface laden with sea spray in order to evaluate the synthetic sea water displacement and corrosion protection capabilities of the experimental formulas. Steel test panels, 2" X 4" (50 mm X 101 mm) conforming to FS 1010 of MIL-S-7952, were used for this test. The test panel was placed so that one 2-inch (50 mm) end was raised one inch (25 mm) above a horizontal surface. The entire panel was sprayed with synthetic sea water consisting of: 50 grams of sodium chloride (NaCl); 22 grams of magnesium chloride (MgCl2 6H2O); 3.2 grams of calcium chloride (CaCl2.2H2O) and 8.0 grams of sodium sulfate (Na2SO4) added to a litre of distilled water. Within one minute after spraying the sea water one milliliter of the test compound was poured along the upper two-inch (50 mm) edge of the panel and allowed to run slowly down the specimen so as to completely cover the test panel. To illustrate AMLGUARD's water displacing ability, the synthetic sea water was tinted red. In Figure 13 the mid portion of the panel had AMLGUARD applied to it. Even at the outset, it can be seen that AMLGUARD is displacing the sea water. After one minute from the initial application, a second milliliter of the test compound was poured and allowed to run down the panel in the same manner. After waiting an additional minute, the panel was hung in a vertical position for one minute. A photo was taken at this time and as depicted by Figure 14, almost all of the sea

water is displaced. The specimen was then placed flat (test side up) above distilled water @ 72°F in a closed desiccator (100% static humidity). After four hours, the panel(s) were removed and cleaned with mineral spirits, and then evaluated for presence of visible corrosion. The effectiveness of the test is best demonstrated by the corrosion on the blank or untreated specimen in four hours versus the sea water displacement and corrosion protection provided on specimens treated with AMLGUARD and exposed for 40 days. These effects are noted in Figure 15.

#### FILM PROPERTIES

## Clarity

Two criteria of the new compound requested by fleet personnel were clarity and dry film properties. The clarity of AMLGUARD relative to other military corrosion preventive compounds, MIL-C-81309 and MIL-C-16173 Grade 4, is illustrated by Figure 2. Evaluation sheets returned by fleet personnel requesting a tint or dye be added to the compound for application discernibility, attests to the compound's effective clarity. The dryness of the material is exhibited by its inability to be removed by rubbing or wiping after it is dry.

#### Removability

The newly developed corrosion preventive compound is removed with solvents such as methyl ethyl ketone, TT-M-261; dry cleaning solvent, Type II. P-P-D-680; 1,1,1 trichloroethane, MIL-T-81533; toluol TT-T-548; aliphatic naphtha, Type II, TT-N-95. All of these solvents are authorized for shipboard use. The solvent emulsion type aircraft cleaners such as MIL-C-43616 could remove the AMLGUARD film depending upon the concentration of the cleaning compound used to clean aircraft surfaces. The surfaces from which the AMLGUARD is removed requires no special preparation other than the usual surface preparation for standard aircraft painting or touch-up. To demonstrate the completeness of the AMLGUARD removal and the non-interference with primer or paint adhesion to substrate, a test was conducted on an untreated 7075 alclad aluminum flexural test assembly, simulating that of an aluminum aircraft skin. The assembly was cleaned by wiping with an acetone dampened cloth. One half of the assembly was left blank or untreated; the other half was treated with AMLGUARD and allowed to air dry at room temperature for three days. The AMLGUARD film was removed by wiping with a toluene dampened cloth, then the entire assembly was sprayed with epoxy primer MIL-P-23377 and air dried overnight. Masking tape was applied across the fastener areas on both the untreated and AMLGUARD treated sides of the assembly. The tape was then removed as a test for paint adhesion. No loss of primer adhesion to the substrate on either side of the test assembly was noted when the tape was pulled away. The assembly was then immersed in distilled water for 24 hours, removed and wiped dry. Within five minutes after removal from the water the tape test was repeated. The primer on both sides of the test assembly was partially removed in equal amounts, again

indicating no change in the adhesion of AMLGUARD. These effects are shown in Figure 16. In a similar test, specification MIL-P-23377 primer was applied over AMLGUARD and the dry tape test performed. The results indicate that the adhesion between the primer and the AMLGUARD is greater than the adhesion between the AMLGUARD and the metallic substrate. Thus, these tests show that AMLGUARD can be effectively removed with no residue remaining behind to interfere with subsequent paint adhesion. This is particularly noteworthy since the compound contains silicone resins.

Advanced surface analytical techniques were conducted at Lehigh University to establish whether solvent cleaning will totally remove silicone resins present in AMLGUARD from metallic surfaces. They are Auger Electron Spectroscopy (AES) and the Electron Spectroscopy for Chemical Analysis (ESCA). In brief, Auger Electron Spectroscopy is a nondestructive method of surface chemical analysis which is accomplished by performing an energy analysis of the electrons ejected from a specimen while bombarding the specimen with a beam of electrons. Electron Spectroscopy for Chemical Analysis (ESCA) is a analytical technique which can be used for quantitative and qualitative studies of the oxidation states of atoms in chemical compounds. The analysis is obtained by measuring energy of electrons that are emitted during irradiation of the sample with X-rays. The tests were conducted on 7075 alclad aluminum coupon specimen measuring 1/2" x 1/2 " x .020" (12.5 mm x 12.5 mm x 0.500 mm) thick. An untreated set of specimens was analyzed to establish a base line on the spectrograms of the elements present in 7075 alclad aluminum. AMLGUARD treated and solvent cleaned specimens were analyzed qualitatively and quantitatively for extraneous (contaminating) elements and elements in excess of those present in the base metal analysis. The treated specimens were sprayed with AMLGUARD, air dried four days and the coating removed by wiping with a solvent dampened cloth. Five different solvents were evaluated. The silicon content on the surface of the specimens after cleaning was determined using the above described methods. Any increase in silicon content of the AMLGUARD treated and cleaned specimens above that of the untreated specimens would be considered due to the silicone residue from the AMLGUARD not being completely removed. Quantitative results of the tests are presented in Table I. The spectrograms corresponding to the determinations below are presented in Appendices G and H. The test results indicate that all traces of silicone were removed with specification solvents, TT-T-548, toluene and TT-T-95, Aliphatic Naphtha, Type II. The specification solvents, MIL-T-81533, 1,1,1, trichloroethane and P-D-680, Dry Cleaning Solvent, Type II removed all but insignificant amounts of silicone. It is believed that quantities found would have been removed with a second solvent wipe. The AMLGUARD treated specimens, solvent cleaned with specification TT-M-261, methyl ethyl ketone appeared to be visibly clean, although, a trace amount of silicon was found. Since highly sensitive spectroscopic procedures were used in this study and no significant amounts of silicon were found, there is no concern for residual silicone causing an adhesion interference when surfaces are properly cleaned with appropriate solvents. Further, Auger Electron Spectroscopy studies at Lehigh University were conducted on 7075 alclad aluminum specimens coated with AMLGUARD and removed with fleet available solvents listed in NAVAIR 01-1A-509. The solvents used for this

AMLGUARD removal evaluation are listed below. The Auger Electron Spectrograms of the solvents used are presented in Appendix I.

- 1. MIL-C-43616 Cleaning Compound, Aircraft Surface (20% Solution)
- 2. MIL-T-81772 Polyurethane Thinner
- 3. MIL-T-19554 Lacquer Thinner
- 4. TT-M-261 Methyl Ethyl Ketone
- 5. TT-I-235 Isopropyl Alcohol
- 6. TT-T-291 Mineral Spirits
- 7. Acetone

Test conditions performed were identical to the first set of specimens sent to Lehigh University for analysis, except these specimens were solvent wiped twice to remove AMLGUARD. Results confirm the findings of the initial test work, that is, proper solvent cleaning will thoroughly remove AMLGUARD from metallic surfaces, including methyl ethyl ketone which initially showed trace amounts of silicon remaining on the metal surface with one solvent wipe. During this second surface analysis it was found that MIL-C-43616 solvent emulsion cleaner did not adequately remove AMLGUARD for subsequent refinishing and should not be used for this purpose, see Naval Air Development Center, Warminster message R122301Z May 78 (Appendix J).

#### PHYSICAL TESTS

# Flexibility

The flexible quality of the AMLGUARD film was evaluated by tests performed using varying conditions. The tests were conducted on 3" x 6" (76 mm x 152 mm) anodized 2024 aluminum, 0.020" (0.5 mm) thick, annealed to produce greater ductility for subsequent mandrel tests. The tests consisted of an AMLGUARD coated test panel subjected to various thermal conditions and bent around various size mandrels. The thermal conditions, film thickness, size of mandrels and test results are listed in Table II. The test results indicate that under extreme bending or flexing conditions the AMLGUARD displays good flexibility properties. The AMLGUARD film did develop some very fine cracks, barely visible to the naked eye. These cracks appeared under the most extreme conditions. There was no loss of AMLGUARD adhesion to the metal substrate.

#### Oil Resistance Test

The following tests were performed to obtain background information on the effects of hydraulic fluids (natural and synthetic) and lubricating oil on the AMLGUARD film. The tests were conducted using specification hydraulic fluids MIL-H-5606 and MIL-H-83282, and specification lubricating oil MIL-L-23699, those in common use on naval aircraft. The test essentially consisted of 3" x 6" (76 mm x 152 mm) 2024 aluminum alclad panels coated with AMLGUARD under conditions listed in Table 3, prior to being subjected to the run-off and immersion tests. The run-off test was designed to simulate a spillage of hydraulic fluids or lubricating oil on an aircraft surface treated with AMLGUARD. The fluid and/or oil was poured over part of an AMLGUARD coated

panel and allowed to run down and off the panel. After four hours dwell time at room temperature, the AMLGUARD film was observed for discoloration or signs of attack from the fluid or oil used. The immersion test utilized an AMLGUARD coated panel whereby one-half of the panel was immersed in the fluid or oil for four hours at room temperature then removed and observed for AMLGUARD film deterioration. The test conditions used during the evaluation and the results obtained are presented in Table III. The hydraulic fluids MIL-H-5606 and M1L-H-83282 had no effect on the AMLGUARD film after the run-off tests at room temperature. The immersion tests performed at room temperature caused the AMLGUARD film to pick up a slightly red tint from the fluids and to display some spotty film removal. The tests conducted at room temperature with the engine lubricating oil MIL-L-23699 did affect the AMLGUARD film considerably. After the run-off test, the lubricating oil had discolored and softened the AMLGUARD film. The immersion test in the lubricating oil caused the AMLGUARD film to be softened so that it could easily be removed with slight rubbing. A four hour immersion test in each of the hydraulic fluids and lubricating oil at 250°F was conducted on AMLGUARD coated panels. At the end of this immersion test both hydraulic fluids and the lubricating oil had caused the AMLGUARD film to wrinkle and permitted its easy removal from the panel in a sheet-like form.

## Effects on Painted Surfaces

The following test was performed to measure the effect of AMLGUARD on aircraft paint. AMLGUARD was applied to a painted panel. The Pencil Hardness Test used in Military Specification MIL-C-43616 was conducted on the paint initially before the application of AMLGUARD and at intervals one-half hour, one hour, and 24 hours after the AMLGUARD application. The pencil hardness taken on the paint film one hour after the compound had been applied was the only interval where the value decreased one pencil hardness. However, the paint film recovered to its original hardness within a 24 hour period. The effect of AMLGUARD on polyurethane paint is comparable to that obtained with specification MIL-C-43616 aircraft washing compounds used at the recommended dilution.

#### Flash and Fire Properties

The flash and fire point tests were conducted on AMLGUARD to establish its flammability characteristics. The flash point test was performed in accordance with ASTM method #D56 using the Tag Closed Cup Tester. The flash point could not be obtained on AMLGUARD with this method, each time the test flame was induced into the cup it was extinguished by boiling or evaporation of the Freon TF (trichlorotrifluoroethane) which is a non-flammable solvent contained in the compound. In a similar test conducted in accordance with the ASTM method D92 which specifies the Cleveland Open Cup Tester the flash point again could not be obtained due to the volatility of the Freon solvent which extinguished the test flame. However, the fire point of AMLGUARD was determined using the Cleveland Open Cup method and found to be 125°F (52°C). This temperature must be attained before ignition or fire of AMLGUARD is possible. Based on these tests, the AMLGUARD compound is considered safe for shipboard use.

# Effects on Acrylic Plastic

Tests were performed in accordance with Military Specification MIL-C-43616 paragraph 4.4.10, to evaluate the effects of ANLGUARD on MIL-P-5425 Acrylic Plastic. The AMLGUARD when tested as specified in MIL-C-43616 did in fact cause craze cracks to form on MIL-P-5425 acrylic plastic test specimens. The testing procedure utilizes a flannel cloth placed at the fulcrum of the test specimen loaded as a simple beam and kept moist with the material for six hours. In a similar test where nothing is placed over the fulcrum the AMLGUARD was applied from an aerosol can on the acrylic plastic test specimens. A total of six coats (one coat per day) and a total dwell time of seven days, showed no evidence of crazing or attack on stressed acrylic plastic test specimens. Based on this evaluation the use of AMLGUARD is safe if an accidental discharge or overspray on acrylic plastic canopies is experienced. However, if large amounts of AMLGUARD are permitted to run off and collect at crevices or like areas damage to acrylic plastic canopies or windshields could result.

# Storage Stability and Shelf Life

Storage stability and shelf life tests on the AMLGUARD compound are currently being conducted at the Naval Air Development Center. They have been in progress for over two years. To date, no deterioration of the AMLGUARD compound is indicated in either the bulk one quart (0.946 liters) glass containers or the 16-ounce (0.476 liters) aerosol or pressurized containers.

#### FLEET EVALUATION

To date over 2500 16-ounce (47.36 X 10<sup>-5</sup>m<sup>3</sup>) aerosol containers of AMLGUARD have been distributed to fleet activities. The pressurized containers of AMLGUARD were packaged and distributed generally in case lots (12 cans/case). Enclosed with each case were six evaluation forms. The input from fleet activities by means of the evaluation forms provided the Naval Air Development Center with the information necessary to determine the quality of the compound and the needs or changes required to meet fleet needs. The consolidated results from the evaluation is presented in Table IV. The U.S. Marines and the U.S. Coast Guard evaluated AMLGUARD primarily as a corrosion preventive on helicopter aircraft. Both services have expressed complete satisfaction and a strong need for the compound as indicated by the recommendation letters and naval messages in the appendices. Aerospace firms are currently evaluating AMLGUARD for use on production F-18 aircraft where MIL-C-16173 Grade 4 is used. The Naval Aircraft Materials Laboratory in Gasport Hamshire, United Kingdom, has expressed an interest in this type of corrosion preventive compound for use on their Sea King helicopters. Several aerosol packages of AMLGUARD were sent to to that foreign facility for their evaluation.

TABLE I. RESULTS OF AUGER ELECTRON SPECTROSCOPY ANALYSIS

	Si*	<u>A1*</u>	Si:Al Ratio
Blank (7075 Alclad Aluminum)	0.072	1.89	0.0380
Toluene (TT-T-548)	0.076	2.03	0.0374
Dry Cleaning Solvent Type II (P-D-680)	0.091	1.96	0.0464
1,1,1, Trichloroethane (MIL-T-81533)	0.086	2.11	0.0407
Methyl Ethyl Ketone (TT-M-261)	0.49	1.65	0.2969
Aliphatic Naphtha Type II (TT-N-95)	0.064	1.66	0.0385

Note: 7075 Aluminum Si (Silicon) content 0.4% max.
7075 Alclad Aluminum Fe (Iron) and Si (Silicon) content 0.7% max.

<sup>\*</sup> Above values obtained from peak to peak deflections measured in inches from the Auger Electron Spectroscopy analysis spectrograms.

# TABLE II. AMLGUARD FLEXIBILITY TEST

	Film		
	Thickness	Bend Over 1/8" Mandrel	Bend Over 1/4" Mandrel
A. I coat air dried 24 hrs. @ R.T.	, "4000.	Good, no adhesion loss, Not tested (1/8" test	Not tested (1/8" test
B. 2 coats air dried 24 hrs. @ R.T.	€ "280000.	or crazing of film	more severe)
C. 1 coat baked @ 240°F/1 hr.	.00045"	Mild lateral cracking	Two mild cracks on one
D. 2 coats baked @ 240°F/1 hr.	<b>)</b> 2000.	along entire length of bend, no adhesion loss	end or bend, no adnession loss
E. 1 coat baked @ 240°F/24 hrs.	.0000.	king, no	Not tested (1/8" test
F. 2 coats baked @ 240°F/24 hrs.	,	adhesion loss	more severe)
G. 1 coat air dried R.T. 24 hrs. flexed @ -60°F	,	Mild lateral cracking	Mild lateral cracking
H. 2 coats air dried R.T. 24 hrs.flexed $^{(d)}$ -60 $^{\rm O}$ F	<b>\</b> 6000.	along entire length of bend, no adhesion loss	along entire length of bend, no adhesion loss
I. 1 coat baked @ $240^{0}$ F/l hr. flexed @ $-60^{0}$ F	.00045"		
J. 2 coats baked @ 240°F/1 hr.flexed @ -60°F		Fine cracking of film	Fine cracking of film
K. 1 coat baked @ 240°F/24 hrs.flexed @ -60°F	,.7000.	along entire length of bend, no adhesion loss	along entire length of bend, no adhesion loss
L. 2 coats baked @ 240°F/24 hrs.flexed @ -60°F			
R.T Room Temperature All tests conducted @ R.T. unless otherwise indicated.	ise indica	red.	

AMLGUARD application:
1 coat from aerosol can
2 coats from aerosol can 1 hr. after first coat.

TABLE III. AMLGUARD OIL RESISTANCE TEST

Immersion lest	MIL-H-5606 Results after 4 hr. subjected @ R.T.	Slight softening of ANICUAND film Slight softening of ANICUAND film Some spotty removal of ANICUAND film No effect on ANICUAND film	MIL-L-23699 Results after 4 hrs. subjected @ R.I.	AMLGUARD film completely removed during	AMIGUACION SOLUTION PROGRAMMENTO PROGRAMMENT	Film easily removed after completion of test	ALMGUARD greatly softened and wrinkles	Film easily removed after completion	No effect on AMLGUARD film	MIL-H-83282 Results after 4 hrs. subjected @ R.T.	AMLGUARD film softened slightly, no	removal evident, film picked up slight fitto for red from hydraulic fluid No effect on ANIGUARD film No effect on AMIGUARD film	
Run Off Test	MIL-H-5606 Results aff	No effect on AMLCUARD film	MIL-L-23699 Results af	Slightly brown discoloration of AMLGUARD film, easily removed	Slightly brown discoloration of AMLGUARD	Brown discoloration of AMLCUARD film,	Brown discoloration of AMLGUARD film,	Brown discoloration of AMLGUARD film,	No effect on AMLGUARD film	MIL-H-83282 Results af	No effect on AMLGUARD film	No effect on AMLGUARD film No effect on AMLGUARD film No effect on AMLGUARD film No effect on AMLGUARD film No effect on AMLGUARD film	
Thickness		.0002" .0006" .00015" .0006" .00035"		.0003"	9000*	.0005	9000*	.0003"	0000.		.0005	.0005.	
		1 cost air dried ( R.T./24 hrs.* 2 costs air dried ( R.T./24 hrs.* 1 cost baked ( 240°F/1 hr.* 2 costs baked ( 240°F/1 hr.* 1 cost baked ( 240°F/24 hrs.* 2 costs baked ( 240°F/24 hrs.*		1 coat air dried @ R.T./24 hrs.*	2 coats air dried @ R.T./24 hrs.*	1 coat baked @ 240°F/1 hr.*	2 coats baked @ 2400F/1 hr.*	1 coat baked @ 240°F/24 hrs.*	2 coats baked @ 240°F/24 hrs.*		1 cost air dried @ R.T./24 hrs.*	2 coats air dried (# R.T./24 hrs.* 1 coat baked (@ 240°F/1 hr.* 2 coats baked (@ 240°F/1 hr.* 1 coat baked (@ 240°F/24 hrs.* 2 coats baked (@ 240°F/24 hrs.*	

R.T. - Room Temperature

\*Oil Resistance Test Run on Test Panels 4 hr. Immersion @ 250°F - The AHLGUARD film on all specimens were attacked by the above fluids and oil. AHLGUARD film wrinkled and lost adhesion on panel, film could then be removed in a skin form.

AMIGUARD Application: 1 cost from serosol can 2 costs from serosol can 1 hr. after first cost.

					NADC-7	8220	-60		pound in sh	pound in brush	be audit, a close has been
									Would like to see this compound in pint or quart cans for brush application.	Would like to see this compound in , pint or quart cans for brush application.	Dye would allow an easy lube audit, however, it is apparent with close examination that AMIGUARD has been applied.
	(6)	VAQ-129	VA-52	VA-52 NAS Whidbey Island	VAW-122	VAW-125	Vs-33	HC-3 NAS North Island	VS-29 on Board U.S.S.	VS-29 on VBoard U.S.S. Enterprise	VP-31 Buno 159505
	Conditions during Exposure H-llumid D-Dry T-Tropical S-Shipboard	1	-/1.8	н/-	-/LB	-/LB	н/гв	H/LB	s/H	8/11	п/гв
FION DATA	Effectiveness of Preservative E-Excellent G-Good Feint W-Unsatisfactory	u	v	g	ш	ш	ω	Unsat/Leaves a Tacky Film on Hinge Areas	ы	ш	9
AMIGUAKD FIELD EVALUATION DATA EVALUATION CRITEKIA	ATION CRITERIA (6) Frequency of Application	Once		Every 7 Days	14 days	One Time in 90 Days	Only the One Time	According to Directions on Can Lable on a One Time per A/C Recorded for this	20-30 Days	Checked every 15 days Reapplied at 30 days	Every 28 Days
	EVALUM (5) Desirable Yes/No	Yes	Yes	Yes	Yes	Yes	Yes		No	Š	Yes
TABLE IV.	(4) Ceneral Appearance S-Satisfactory U-Unsatisfactory	Unsat/Lack of Dye, Impossible to Tell Where Applied	vs.	ø	Unsat/In Clear Form Hard to Tell if Entire Area is	S	vs	ø	Ø	ø	os
	(1) Cleaning Procedure Prior to AMIGUARD Application	None	Wipe Down Before Application	Washed	A/C Washed, 01d Grade IV Removed W/P-D-680	Removal of Grade IV w/P-D-680	Entire A/C Wash Job, Removal of Corr. & Specific Area Cleaned	A/C Washed where AMLCUARD applied Cleaned w/mild Cleaning Solvent	Normal Fresh Water Wash	Removed Paint Feathered Edges Cleaned with Aliphatic Naphtha	Wiped with A Dry Rag
	(2) Areas Applied	Port MLG Strut Buno 158800	Springs & Hinges on 7	Hinges 6 Springs, Bare Metal Areas	Hyd.B-Nuts & Hdwe in Wheel Wells & Wing Butts	Wing Butts, Landing Gear	Bare Screws, Hinges Ordnance Hdwe	Fwd Head & Trans Battery & Camlocks., Free Air Gauge on Windshield	Wheel Wells	4" Square of Bare Metal on Str'd Mid Fuselage on A/C 706 159386	Piano Hinges, Hi Loc Fasten- ers Tail Area Anchor nuts - Tail Section
	(1) Aircraft Type	EA-68	A-6E	A-6E	2 13	E-2C	42 4.	СН-46	S-3A	S-3A	P-3C
		ن	2.	÷	4	٠,	•		<b>.</b>	•	9

		Needs a Dye Bad, You Can't See It	Needs a Dye bad, You Can't See It		NA DC - 78220 - 60								NADC-78220-60						
3	Activity	UP-40 NAS Moffet Field	UP-40 NAS Moffet Field		VP-48 Air- Frames NAS Moffet Field	VP-48 Air- Frames NAS Moffet Field	VP-31 Buno 150511		VP-19 NAS Moffet Field	VMFA-314	VMA-214	UMA-311 Metal Shop	AIRANTISUBRON- 31 on USS Independence CV62	HEMS-13 Flight Line	VX-4 NAS PL, Mugu, CA				
(8)	Conditions during Exposure II-Ilumid D-Dry T-Tropical S-Shipboard LB-Landbased	ist Time H/B 2nd Time D/LB	н/гв		-/LB	D/LB	н/гв		-/LB	D/LB	D/LB	D/LB	s/-	D/LB	H/LB Sub-Tropi- cal				
DATA (7)	iveness f vative ent od ir sfactory	9	IJ		ш	<b>LLI</b>	3		ш	ы	ш	9	w	v	E Displaces Water Very Well				
AMIGUARD FIELD EVALUATION DATA EVALUATION CRITERIA (5)	ency	lst Time 4/28/76 2nd Time 5/20/76	lst Time 4/28/76 2nd Time 5/18/76				28 Days			14 Days	14 Days	Tvice	On every 56 & 112 Day Inspec- tion & Touchup When Needed	Twice Monthly					
_	Dye Destrable Yes/No	Yes	Yes		Yes	Yes	Yes		Yes	No	2	2	o N	No	χes**				
TABLE 1V. (4)	Ceneral Appearance S-Satisfactory U-Unsatisfactory	Ø	Ø		ø	Ø	ø		vs	s	w	ø	ø	s	aned S*				
ĉ	Cleaning Procedure Prior to AMLCUARD Application	C/P Flapwells, Wiped Heavy Depo- Wheel Wells,AFT sits of Oil and Fuselage Grease Away	Wiped Heavy Deposits of Oil and Dirt off 4/28/76		Regular A/C Wash Cycle	Regular A/C Wash	Wipe w/Dry Rag on Piano Hinges, None on Anchor Nuts or Hi Lock Faste- ners		Applied after A/C was Washed	Dry Cleaning Solvent	Cleaned with Abra- sive Webbing & A/C Washing	None	Removed all Dirt, Salt Spray 6 01d Preservative with Toluene	Wash	Some Areas were Cleaned & Dried, Some were left Wet & Dirty or Just Wiped Off, AML- GUARD under both Conditions Covered				
(2)	Areas Applied C	C/P Flapwells, Wheel Wells,AFT Fuselage	QE-6 Port Whell Well Down Lock, Nose Wheel Well Chipped Paint	Stbd lnbd M/M Lip Bolts, QE-2 Heat Exch Access Lips	All Hinges	All Hinges	Plano Hinges 6 Fasteners, Hi-Lock Fasteners, Anchor Nuts	in Tail Area	Tail Section 6 All Hinges 6 Cables	Hinge Pins, Screws	Fuel Probe, Cables	Slat Tracks & Rollers Piano Hinges	Hdwe in Wheel Wells, Wing Butts, Fast- eners, Cables, Finfold & Wing Panels	Hinges, Slat Track Rollers	All Skin Sur- faces 6 Landing Gear				
8	Aircraft Type	P3C 157325 QE-2	P3C Buno 159326 QE-6		P3C 158226 •	P3C 158221	M.				44	A4H	53A Viking	A4H TA4F	F14, F4, TA-4, G-1A & US-2				
		ii	13.		13.	14.	i 1	.4	16.	17.	.81	.61	20.	21.	25.				


(9) Elvity	USCC Aviation Exterior of all elec Training connectors, a'l area Center Prime metal, gear boxes,ro Unit, Mobile, tail drive shaft, ba Alabama bolts, clamps, and e
e e e e e e e e e e e e e e e e e e e	USCG Aviat Training Center Pri Unit, Mobi Alabama
Fig. 100 (8) (9)  Effectiveness Conditions of during Preservative Exposure C-Good T-Tropical F-Fair S-Shipboard Activity	s/-
eness itive it	•
Effectiveness of Preservative E-Excellent G-Good F-Fair U-Unsatisfactory	ш
TABLE 1V. AMICUARD FIELD EVALUATION DATA  (5) (6) (6) Effect ce Dye Frequency o tory Desirable of Preser ctory Yes/No Application E-Excell G-Go F-Fa	Once before Deployment and as Needed dur- ing 4 Houth Deployment (Reapplied Twice)
1V. ANILUG EVALUZ (5) Uye Desirable Yes/No	۲e s
(4) Cuncra! Appearau. S-Satisfac U-Unsatisfa	Very S
(1) (2) (3) Aircraft Type Areas Applied Cleaning Procedure Prior to AMGUARD Application	Complete Soap & Solvent Cleaning Prior to First Application, Local Cleaning as Needed for Subsequent Application
Areas Applied	0044044
(1) reraft Type	De la companya de la
4	Helicopter HH-52A



FIGURE 1. PARTIALLY PROTECTED 1010 STEEL PANEL EXPOSED TO 5% SALT SPRAY ENVIRONMENT FOR SEVEN DAYS

RIGHT SILE OF EACH PANEL TREATED WITH MATERIAL IDENTIFIED ABOVE IT, LEFT SIDE UNTREATED


FIGURE 2. LIGHT/DARK GRAY PAINTED PANELS TREATED WITH AIRCRAFT CORROSION PREVENTIVE COMPOUNDS




AMLGUARD TREATED

UNTREATED

FIGURE 3. PARTIALLY PROTECTED 1010 STEEL PANEL EXPOSED TO 5% SALT SPRAY ENVIRONMENT FOR SEVEN DAYS





1010 STEEL TREATED WITH "AMLGUARD," SUBJECTED TO 100% RELATIVE HUMIDITY @ 120°F FOR 65 DAYS. "AMLGUARD" REMOVED WITH MINERAL SPIRITS FROM PANELS ON LEFT SIDE TO SHOW PROTECTION AFFORDED. FIGURE 5.





FIGURE 6. EQUIPMENT FOR SULFUROUS ACID/SYNTHETIC SEA SPRAY TEST









FIGURE 8. SIMULATED CARRIER DECK ENVIRONMENT H2SO3/SEA SPRAY TEST



# SPECIMEN TREATED WITH AMLGUARD DEPICTING TYPICAL SALT DEPOSITS AFTER 5 TEST CYCLES

FIGURE 9. SULFUROUS ACID SYNTHETIC SEA WATER SPRAY TEST SPECIMEN





FIGURE 10. ACCELERATED LABORATORY TEST SIMULATED CARRIER DECK ENVIRONMENT



### AS REMOVED FROM CABINET

FIGURE 11. PROTECTED AND UNPROTECTED 7075 ALUMINUM PANELS AFTER 90 DAY EXPOSURE TO 5% SALT/SO2 SPRAY (AS REMOVED FROM CABINET). NOTE: PAINT BLISTERS ALONG SCRIBED MARKS ON UNPROTECTED (LEFT) PANEL.




FIGURE 12. PANELS PICTURED IN FIGURE 11 AFTER SOLVENT WIPING. PROTECTED AND UNPROTECTED 7075 ALUMINUM PANELS AFTER 90 DAY EXPOSURE TO 5% SALT/SO2 SPRAY (AS REMOVED FROM CABINET) AFTER SOLVENT WIPE.




SYNTHETIC SEA WATER DROPLETS
(TINTED)

(TINTED)

SYNTHETIC SEA WATER
BEING DISPLACED BY AMIGUARD

1010 STEEL SPECIMEN

FIGURE 13. SYNTHETIC SEA WATER DISPLACEMENT TEST



1010 STEEL SPECIMEN

FIGURE 14. SYNTHETIC SEA WATER DISPLACEMENT TEST

TREATED

UNTREATED

NADC-78220-60

SEA WATER
NOT DISPLACED

4 HOUR EXPOSURE


SEA WATER EFFECTIVELY DISPLACED AND PROTECTED BY AMIGUARD

40 DAY EXPOSURE

FIGURE 15. SYNTHETIC SEA WATER DISPLACEMENT PANELS AFTER EXPOSURE TO 100% HUMIDITY



. \_



PRIMER ADHESION COMPARISON RESULTS

FIGURE 16. WET TAPE TEST

APPENDIX A

FITRON THREE TWO Message 120303Z Aug 76

PLCEIVED

1976 /13 12 C5 O1

RITERYUM RULYSGG8259 2250324-EEEE--RUEODOA: TAV FEEEE DEWIN. = 1273737 AUG 76 we Livin FM FITTOY THREE TWO TO RUEDALL/COMVAVAIRLANT NORFOLK VA INFO ZEN/COMCARAIRWING ONE ZENV 155 JOHN F KENNEDY FUEBEDA/COMFITZING DNE DCEANA VA RULSFAA/COMMAVAIRSYSCOM WASHINGTON DC PUEDDOANNAVAIRTEVOEN WARMINSTER PA FUELS\_1/NAVAINGAONKEAU NOMFOLK VA FUEBEDA/FITRON THREE TWO DET OCEANA VA UNSELS E F T 0 //N13929// COMMAYAIRSYSCOM FOR AIR-52832B; MAVAIRDEVCEN FOR CODE 382B; COMMANAIRLANT FOR CODE 5288. AML-SUARD EVALUATION 4. COMNAVAIRLANT NORFOLK VA 111352Z JUN 76 1. REF A DESIGNATED FITRON THREE TWO TO CONDUCT EVALUATION OF AMERGUARD CORPOSION PREVENTIVE; 2. EVALUATION CONDUCTED 9 JULY TO PRESENT IN CARRIER OPS/ MARITIME ENVIRONMENT: AML+GUARD APPLIED TO BROKEN AND

PAGE 32 RULYSGG6259 UNCLAS E F T O CHIPPED PAINT ON ALL AREAS OF F144 INCLUDING INTAKES, MINGS, SPEED BRAKES, AND TURTLEBACK, ALSO APPLIED TO GUN BLAST DEFLECTOR AND TO LEADING EDGES OF WINGS AND BOTH FORIZONTAL AND VERTICAL STABILIZERS: 3. AMERE AML-GUARD APPLIED TO BROKEN/CHIPPED PAINT, CORROSION IS DRASTICALLY REDUCED; AML-SUARD ON LEADING EDGES DECREASES MAINTENANCE TIME BY 90 PERCENT OF THAT PREVIOUSLY DEDICATED TO UPKEEP OF LEADING EDGES: AML-GUARD SHOULD BE REAPPLIED AFTER AIRCRAFT WASHING AND AT APPROX 12 DAY INTERVAL ON CEADING EDGES: SPOY PEELING OCCURS DUE AFRODYNAMIC FRICTION AND ABPASION FROM WASHING PADS, GUN BLAST DEFLECTOR ONLY AREA WHERE AME-GUARD DOES NOT PERSIST DUE BURN-DEF; HOWEVER, CLEANING OF DEFLECTOR GREATLY FACILITATED WHERE PORTIONS OF AML-GUARD REMAINED; 4. RECOMMEND THAT AME GUARD BE ACCEPTED FOR FLEET USE AND PROCURED IN ONE GALLON QUANTITIES AS WELL AS 16 DUNCE AEROSOL CANS. FT #6259

TOR: 1206017/EB/JM COG: 30

REF A: SAME SUBJECT

1 4 AUG 1375

R 1203037 AUG 76

APPENDIX B

COMNAVAIRLANT Message 170952Z Dec 76

RECEIVED

1976 DEC 17 23 55

PITEZYUN RUEDALA5953 3522240-EEEE--RUEODOA: TNY FEFEE NA VAIRDE VOEN P P 1779527 PEC 76 MSG CHIR FH COMNAVAIRLANT NORFOLK VA TO RULSSAA/COMMAVAIRSYSCOM WASHINGTON DC INFO RULSSAA/CHNAVMAT WASHINGTON DC PUMMAPHICOMNAVAIRPAC SAN DIEGO CA PUFCTGA/NAVAIRDEVCEN WARMINSTER PA "JESHGA/GSA WATHINGTON DC PUESAGRIASO PHILADELPHIA PA PUEDLFA/CG FMFLANT FUTUALIZES SECOND MAW RUSBNMA/MAG TWO SIX FUELEDA/COMFITHING ONE OCEANA VA FUELEDA / FITRON THREE TWO UNCLAS E F T O //N13DAD// COMMANAIRSYSCOM FOR AIR 5283281 NAVAIRDEVEN FOR 3029 AML GUARD PROCUREMENT A. FITHON THREE TWO 120363Z AUG 76 NOTAL MAS TAD SIX 152155Z DEC 76 PASEP IN VIEW OF FAVORABLE EVAL INDICATED REFS A AND B REQUEST

FAGE 2 RECOALA5953 UNCLAS F F T O //N13428//
EXPENITIOUS PROCUREMENT SUBJ MATERIAL, AME GUARD IS SUPERIOR TO
ANY DOPROSION PREVENTIVE COMPOUND CURRENTLY UTILIZED ON LAND/SEA
TASET FIRCHAFT:
T. FETCHMEND SUBJ MATERIAL PE PROCURED IN ONE QUART CONTAINER AND
16 OZ AEFOSOL CANS;
BT
#5953

MAN

TOR: 1723557/JM/JP/PP REF A: NOT HELD B: SAME SUBJ COS: 30 -I-: 12 108 20000

P R 1709527 DEC 76

APPENDIX C

COMNAVAIRPAC Speedletter FF7-11/N71A/DRR:ps 10320 ser 1539 of 6 Oct 1976 OCT 6 1375

FT7-11/M71A/DRR:ps 10320 Ser 1539

Commander Naval Air Force U.S. Pacific Flaet (Code 74F) Naval Air Station, North Island San Diego, CA 92135

Subj: AME-GUARD Corrosion Preventive Compound Evaluation; report of

Ref: (a) COMNAVAIRPAC 211304Z AFR 76

Encl: (1) VS-33 spdltr EPD:jdb 2857 ser 267 of 1 JUL 76

(2) AMLGUARD Evaluation Report Form, HC-3

- 1. Reference (a) directed evaluation of the AMLGUARD Corrosion Preventive Compound. In accordance with reference (a), enclosures (1) and (2) are forwarded.
- 2. AMLGUARD is considered to be excellent as a temporary film for surfaces where the paint has been damaged, and immediate repainting cannot be accomplished. The addition of a tint would be advantageous for identifying surfaces coated with the protective film.

By direction

Frantel

Commander Anti-Submarine Warfare Wing U.S. Pacific Fleet Naval Air Station, North Island San Diego, CA 92135 ---- ADDRESS

.....

REPLY AS SHOWN AT LEFT: OR, REPLY HEREON AND RETURN

". Mesogs towards and deep a page, it is

I need to meed received, a conpleting and a contain the con-L need to be to be the contained and a contained to be to be a war ket marks as to a walk we to be presented to be a belong to prediction of one has a to be of regular corresponder.

CLASSIFICATION

APPENDIX D

CG Aviation Training Center Letter (PH: FTS 534-9209) 13081 of 18 October 1977



# DEPARTMENT OF TRANSPORTATION UNITED STATES COAST GUARD

MAILING ADDRESSCOMMANDING OFFICER
U.S. COAST GUARD
AVIATION TRAINING CENTER
MOBILE, ALABAMA 35508
(PH: FTS 534-9209)

13081 18 October 1977

From: Commanding Officer, CG Aviation Training Center
To: Naval Air Development Center, Aero Materials Lab

(code 606) Warminster, Pennsylvania 18974

Subj: AMLGUARD (MIL-C-85054); evaluation of

- 1. During a recent helicopter deployment on board a Coast Guard Icebreaker AMLGUARD was substituted for MIL-C-16173D. This substitution provided an evaluation of subject material while exposed to a corrosive environment. Subject material was used extensively on one helicopter while MIL-C-16173D was used on the other.
- 2. Upon return from deployment the helicopter was thoroughly inspected for any corrosion. There was no corrosion found that could have been caused by a lack of protection provided by AMLGUARD. The transparency of AMLGUARD made this inspection an easy task.
- 3. The advantages of AMLGUARD are that it will provide the necessary protection, will not collect dust and other contaminants, and is transparent, so that any corrosion, cracks, or other defects can be detected without removal of subject material.
- 4. Request you advise when subject material becomes available through normal supply channels. We intend to recommend that Commandant (G-EAE), U. S. Coast Guard approve AMLGUARD for use on all U. S. Coast Guard Aircraft.

Encl: Evaluation Report

Copy to: COMDT G-EAE/63 CO AVENGDIV AR&SC APPENDIX E

COMNAVAIRPAC Letter 10360 WPC B14892 Ser 74F/5137 of 7 Sep 1976



# COMMANDER NAVAL AIR FORCE UNITED STATES PACIFIC FLEET NAVAL AIR STATION. NORTH ISLAND SAN DIEGO. CALIFORNIA 92135

10360 WPC B14892 Ser 74F/ **5 1 37** 

FIRST ENDORSEMENT on CG THIRD MAW 1tr 49:SAC:rem 10322 of 18 Aug 1976

From:

Commander Naval Air Force, U.S. Pacific Fleet

To:

Commander Naval Air Development Center

Sub.i:

Service Evaluation of AMLGUARD Corrosion Preventive Compound

1. Forwarded, recommending acceptance of the subject material for fleet use.

2. Field evaluation reports received thus far have been unanimous in their conclusion that the material designed as "AMLGUARD" is highly satisfactory for applications that normally require frequent application of MIL-C-81309 water displacing preservative.

direction



### APPENDIX F

3D Marine Aircraft Wing, FMFPAC Letter 49:SAC:rem 10322 of 18 Aug 1976

.

----



### **UNITED STATES MARINE CORPS** 3D MARINE AIRCRAFT WING, FMFPAC MCAS, EL TORO

SANTA ANA, CALIFORNIA 92709

IN REPLY REFER TO: 49:SAC:rem 10322

AUG 18 1976

From: Commanding General

To: Commander, Naval Air Developement Center (Code 30222)

Commander, Naval Air Force, U. S. Pacific Fleet (Code 74F) Via:

Subj: Service Evaluation of AMLGUARD, a clear water displacing corrosion

preventive compound

Ref: (a) NAVAIRDEVCEN 1tr 3022/2857 dtd 7 April 1976

COMNAVAIRPAC 211804Z APR 76

1. In accordance with reference (a) request, modified by reference (b), this activity has completed an evaluation of AMLGUARD.

2. Evaluation was conducted by several squadrons with A-4M, TA-4F, and F-4N aircraft. All personnel connected with the evaluation were highly satisfied with the product and desire that it be placed in the supply system and all hands be notdfied of National Stock Number assigned when available.

- Areas to which AMLGUARD was applied included fuel probes, cables, piano\_type hinge pins, slat tracks and rollers, screws, etc.. In every case, AMIGUARD was as good as to better than MIL-C-81309.
- 4. 3quadron evaluation sheets are attached.


J. a. Porter G . A . PORTER By direction

APPENDIX G

Auger Electron Spectroscopy

# AUGER ELECTRON SPECTROSCOPY

SPECTROGRAMS OF 7075 ALCLAD ALUMINUM AFTER AMIGUARD APPLICATION AND SOLVENT WIPE REMOVAL TREATMENT




APPENDIX H

ESCA (Electron Spectroscopy Chemical Analysis)

# ESCA (ELECTRON SPECTROSCOPY CHEMICAL ANALYSIS)

SPECTROGRAMS OF 7075 ALCLAD ALUMINUM AFTER AMIGUARD APPLICATION AND SOLVENT WIPE REMOVAL TREATMENT




BINDING ENERGY

APPENDIX I

Auger Electron Spectroscopy

# AUGER ELECTRON SPECTROSCOPY

SPECTROGRAMS OF 7075 ALCIAD ALUMINUM AFTER AMIGUARD APPLICATION AND SOLVENT WIPE REMOVAL TREATMENT



APPENDIX J

NAVAIRDEVCEN Message 122301Z May 78

NADC-78220-60 RTTUZYUW RUEODQA2505 1322301-UUUU--RUEOAIG RUEOALL RUWJELC RULSSAA RUEBRDA RUWMBFA RUCLEKA RUEOALA RUWJELA RUCLMHA. ZNR UUUUU R 122301Z MAY 78 FM NAVAIRDEVCEN WARMINSTER PA ROUTINE OUTGOING TO RUEDAIG / NAVAIREWORKFAC CHERRY POINT NC INFO RUECALL/COMNAVAIRLANT NORFOLK VA RUWJELC/COMNAVAIRPAC SAN DIEGO CA RULSSAA/COMNAVAIRSYSCOM WASHINGTON DC RUEBRDA/NAVAVNLOGCEN PATUXENT RIVER MD RUWMBFA/NAVAIREWORKFAC ALAMEDA CA RUCLEKA/NAVAIREWORKFAC JACKSONVILLE FL RUEOALA/NAVAIREWORKFAC NORFOLK VA RUWJELA/NAVAIREWORKFAC NORTH ISLAND CA RUCLMHA/NAVAIREWORKFAC PENSACOLA FL BT UNCLAS //N10360// COMNAVAIRLANT FOR CODE 528; COMNAVAIRPAC FOR CODE 74; COMNAVAIRSYCOM FOR AIR-5203; NAVAVNLOGCEN FOR CODE 310; NAVAIREWORKFACS FOR CODE 340 MIL-C-85054 CORROSION PREVENTIVE COMPOUND REMOVAL A. NAVAIREWORKFAC CHERRY POINT NC 271954Z APR 78 B. NAVAIRDEVCEN WARMINSTER PA 071900Z MAR 78. C. NAVAIR 01-1A-509 1. IAW REF A, INFORMATION PROVIDED IN REF B MAY HAVE BEEN MISINTERPRETED SINCE REF A CITES PARTIAL REMOVAL OF SUBJ MATERIAL BY METHYL CHLOROFORM AND DRY CLEANING SOLVENT. IN EACH CASE, AN INSIGNIGICANT AMOUNT WAS

1. IAW REF A, INFORMATION PROVIDED IN REF B MAY HAVE BEEN MISINTERPRETED SINCE REF A CITES PARTIAL REMOVAL OF SUBJ MATERIAL BY METHYL CHLOROFORM AND DRY CLEANING SOLVENT. IN EACH CASE, AN INSIGNIGICANT AMOUNT WAS DETECTED ONLY BY HIGHLY SENSITIVE SPECTROSCOPIC PROCEDURES. THE SOURCE OF THE SI DETECTED COULD HAVE BEEN DUE TO ATMOSPHERIC CONTAMINATION. NORMAL CLEANING WITH THESE SOLVENTS AS WELL AS TOLUENE AND ALIPHATIC NAPHTHA WILL PROVIDE A SUBSTRATE SUITABLE FOR APPLICATION OF COATINGS OR ADHESIVES. THESE SOLVENTS/THINNERS ARE LISTED IN REF C. AVAILABILITY TO FLEET CONFIRMED BY TYCOMS.

2. AS REF B INDICATED, ADDITIONAL SOLVENTS/THINNERS WERE TESTED FOR REMOVABILITY OF SUBJ MATERIAL. THE FOLLOWING WERE FOUND TO THOROUGHLY REMOVE THE SUBJ MATERIAL FROM THE TEST SURFACES: MIL-T-19544 THINNER, MIL-T-81772 THINNER, ACETONE, ISOPROPYL ALCOHOL, MINERAL SPIRITS, AND METHYL ETHYL KETONE. THE METHYL ETHYL KETONE WAS FOUND TO BE SATISFACTORY UPON FURTHER CHECK. PATNT ADHESION TESTS CONFIRMED THE ANALYTICAL RESULTS. ALL MATERIALS ARE LISTED IN REF C. MIL-C-43616 SOLVENT EMULSION CLEANER DID NOT REMOVE THE SUBJ MATERIAL ADEQUATELY FOR REFINISHING AND FLEET UNITS ARE ADVISED NOT TO USE IT FOR THIS PURPOSE. ALL SOLVENTS/THINNERS LISTED HEREIN ARE RECOMMENDED FOR REMOVAL OF SUBJ MATERIAL.

SUBJ MATERIAL.

BT TOD: 122340Z MAY 78/JG/EB/JB

#2505 RELEASED BY: P.M. STURM
DRAFTED BY: J. CARROLL

CC. 60

R 1223Ø1Z MAY 78

### APPENDIX K

Procedures for Use of MIL-C-85054(AS) (AMLGUARD) for Aircraft Corrosion Prevention/Control

## PROCEDURES FOR USE OF MIL-C-85054(AS) (AMLGUARD) FOR AIRCRAFT CORROSION PREVENTION/CONTROL

### A. Description

Mixtures of corrosion inhibitors and water displacing compounds in an organic resin vehicle dissolved in suitable solvents which produce a transparent, water displacing, flexible, non-tacky corrosion preventive film. This material is usually tinted to increase the detectability of resultant films on aircraft surfaces without adversely affecting its properties.

### B. Material Forms Available

Type I

16 ounce aerosol can NSN: 8030-01-041-1596

Type II

1 quart (bulk) can

MSN: 8030-01-045-4780

### C. Methods of Application

Brush, dip, spray
For spray application, do not thin (dilute) bulk material.

### D. Application Instructions

For best results:

- 1. Wipe off dirt and excess moisture from surface to be protected prior to applying the corrosion preventive compound.
- 2. Apply a thin, uniform coat of corrosion preventive compound directly on area to be protected.
  - 3. Allow to dry for one-half hour.
- 4. Apply a second uniform coat of corrosion preventive compound and allow to dry.
  - 5. Application by wiping is not recommended.
- 6. After application of each coat of material by aerosol spray can, clear the spray tip (nozzle) of entrapped material by inverting the can and spraying.

### E. Removability

These materials are easily removed by the following solvents and will not leave a residue:

Methyl ethyl ketone	TT-M-261	
Aliphatic naphtha	TT-N-95	
Mineral spirits	TT-T-291	
Dry cleaning solvent	P-D-680	70029018
Isopropyl alcohol	TT-I-735	
Acetone	0-A-51	
Thinner	MIL-T-19544	
Thinner	MIL-T-81772	

### CAUTION:

Do not use synthetic wiping cloths with these solvents to remove MIL-C-85054 films.

### F. Intended Uses

Materials conforming to MIL-C-85054 can be substituted for MIL-C-81309 or MIL-C-16173, (Grade 4) except on parts which require a lubricated surface, electrical contact areas, form-in-place gaskets, and removable fasteners as described in Table I.

Specific areas on which these materials have been satisfactorily used are:

Wing butts, wheel wells, wheels, leading edges, access panels, exterior of electrical connectors, exterior of gear boxes, rotor heads, bolts, clamps, landing gear, cables, accessory gearbox of power plants, installed permanent fasteners, seams, chipped/damaged paint metal surfaces, chassis, mounting racks, hardware, bus bars, and terminal boards.

### G. Endurance

MIL-C-85054 is a short term preservative and must therefore be reapplied more frequently in an outdoor sea environment.

TABLE I

EXPLANATION OF RESTRICTED AREAS OF APPLICATION

ML-c-16173 Grade 4	ON	NO NO	NO	YES
MIL-C-81309	*YES	XES NO	SELX*	YES
MIL-C-85054	NO	NO NO	NO	ON (
PARTS/AREA	Lubricated surface	Electrical Contacts Friction/Sliding Stationary (points)	Form in Place Gaskets	Removable Fasteners (thread area)

\* Where lubrication is essential, VV-L-800 is used. MIL-C-81309 shall be used where corrosion protection and water displacement are primary considerations.

### DISTRIBUTION LIST

### REPORT NO. NADC-78220-60

### AIRTASK NO. WF54-593-201 WORK UNIT NO.ZM301

	No. of Copies
COMNAVAIR (AIR 954)	10
COMNAVAIRLANT (Code 528)	12
COMNAVAIRPAC (Code /4F)	12
CONAVAIREWORKFAC, Alameda (Codes 120, 300, 340, 940)	1
Jacksonville (Codes 120, 300, 340, 940)	1
Norfolk (Codes 120, 300, 340, 940)	1
North Island (Codes 120, 300, 340, 940)	1
Pensacola (Codes 120, 300, 340, 940)	1
Cherry Point (Codes 120, 300, 340, 940)	î
CONRL (Codes 6313 and 6120), Washington, DC	2
WPAFB (AFML), Dayton, Ohio 45433	1
WRAMA (Code MMETC), Robins AFB, Georgia 31098	1
CO, Army Materials Engineering R&D Center, Ft. Belvoir, VA.	i
CO, Army Aviation Systems Command, St. Louis, MO 63100	1
DDC	12
Commandant (G-EAE/63) U. S. Coast Guard Headquarters, 400 Seventh St. S.W., Washington, DC 20590	6
CO, U.S.C.G. Aviation Training Center (Prime Unit), Mobile, AL 36608	2
Fleet Analysis Center (Code 8613), Naval Weapons Station, Seal Beach, Corona Annex, Corona, CA 91720	1
COMNAVAIRENGCEN (Code 91222), Lakehurst, NJ 08733	2
COMNAVAIRSHIPENGCEN (Code 6101C), Washington, DC 20362	1
Vought Corporation, Unit 2-53-400, Box 5907,	
Dallas, Texas 75222	1
CG, 2nd Marine Division (Attn: Major Sahno (G-4)	

### DISTRIBUTION LIST (CONT'D)

### REPORT NO. NADC-78220-60

### AIRTASK NO. WF54-593-201 WORK UNIT NO. ZM301

	No. of Copies
San Antonio Air Force Logistics Center, Bldg. 171/MMETT Kelly Air Force Base, Texas 78241	1
U.S.C.G. Aircraft Repair Supply Center (LCDR Webster) Elizabeth City, North Carolina 27909	1
COMNAVELEXSYSCOM, Washington, DC 20360	1
COMNAVFACENGCOM, Washington, DC 20374	1
COMNAVSEASYSCOM, Washington, DC 20362	1
COMNAVSUPSYSCOM, Washington, DC 20376	1